IE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors: DANIEL SELIGSON

Group Art Unit: 3674

Patent No.: US 6,940,501 B2

For:

NOV 1 0 2005

§ Examiner:

Ali A. Zamani

Issued: September 6, 2005

888888888

-

Atty. Dkt. No.:

ITL.0429US (P9135)

Commissioner for Patents P.O. Box 1450

Alexandria, VA 22313-1450

TILED DISPLAY

Attn: Decision and Certificate of Correction

Branch of the Patent Issue Division

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 C.F.R. § 1.322(a))

- 1. Attached, in duplicate, is Form PTO-1050, with at least one copy being suitable for printing.
- 2. The exact page and line number where the errors are shown correctly in the application file is in the Reply to Paper No. 7, page 2, claim 8 (renumbered in the printed patent to claim 7), line 1 and page 4, claim 17 (renumbered in the printed patent to claim 19), line 1.
 - 3. Please send the Certificate to:

Timothy N. Trop TROP, PRUNER & HU, P.C. 8554 Katy Freeway, Suite 100 Houston, Texas 77024-1805 Certificate
NOV 1 6 2005
of Correction

Date of Deposit:

I hereby certify under 37 CFR 1.8(a) that this correspondence is being deposited with the United States Postal Service as first class mail with sufficient postage on the date indicated above and is addressed to the Commissioner for Patents, P.O. Box 1450, Alexandria VA 22313-1450

Sherry Tipton

4.	All errors	sought	to be	corrected	were	made	in	printing	by	the	Patent	and
Trademark Office and no fee is believed to be due.												

Respectfully submitted,

Date: ///8/05

Timothy N. Tros, Registration No. 28,994 TROP, PRUNER & HU, P.C.

TKOP, PRUNER & HU, P.C. 8554 Katy Freeway, Ste. 100

Houston, TX 77024 713/468-8880 [Phone] 713/468-8883 [Fax]

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,940,501 B2

DATED : Setpember 6, 2005

INVENTOR(S) : Daniel Seligson

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6: Line 28, "7" should be --6--. Line 66, "12" should be --14--.

MAILING ADDRESS OF SENDER (Please do not use customer number

PATENT NO. US 6,940,501 B2

Timothy N. Trop Trop, Pruner & Hu, P.C. 8554 Katy Freeway, Suite 100 Houston, Texas 77024 No. of additional copies

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,940,501 B2

DATED : Setpember 6, 2005

INVENTOR(S) : Daniel Seligson

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6: Line 28, "7" should be --6--. Line 66, "12" should be --14--.

MAILING ADDRESS OF SENDER (Please do not use customer number

PATENT NO. US 6,940,501 B2

Timothy N. Trop Trop, Pruner & Hu, P.C. 8554 Katy Freeway, Suite 100 Houston, Texas 77024 No. of additional copies

NOV 1 8 2005